


## L-Shap Gapless Connector

o for FCOB LED Light Strip



## L-Shap Gapless Connector



## Open the retaining clips on both sides










Cut the light strip along the cutting line



Adjust the contact position to ensure that the positive and negative strip are in full contact with the 2 copper contacts



Make sure that the positive pole is connected to the positive pole, then press down the retaining clips



Please pay attention to align the positive and negative poles of the FCOB light strip



**PACKAGE: 4 PCS CONNECTORS**